

Caerus Piceance LLC
E13W
Location # 334900/334910



Location



location



**Caerus Piceance LLC
E13W
Location # 334900/334910**



Location



location/ lack of battery signage



Caerus Piceance LLC
E13W
Location # 334900/334910



Location/ lack of battery signage



location



Caerus Piceance LLC
E13W
Location # 334900/334910



Load lines lacking bull plug



Load lines lacking bull plug



Caerus Piceance LLC
E13W
Location # 334900/334910



Load lines lacking bull plug



Load lines lacking bull plug



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
E13W
Location # 334900/334910



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus Piceance LLC
E13W
Location # 334900/334910



Lack of stabilization/compaction



Lack of stabilization/compaction



Caerus Piceance LLC
E13W
Location # 334900/334910




Open ended piping for thawing out dump lines on tanks with exhaust from trucks.



Open ended piping for thawing out dump lines on tanks with exhaust from trucks.



**Caerus Piceance LLC
E13W
Location # 334900/334910**



Open ended piping for thawing out dump lines on tanks with exhaust from trucks.



Glycol vessel lacking labeling

