

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Watson Ranch B Pad /

Location ID: 440705



Photo #5193 from entrance to location.



Photo #5194 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Watson Ranch B Pad /

Location ID: 440705



Photo #5195 Unused chemical tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources