

Interim Reclamation Inspection

November 16, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 435424

Inspection Document #: 697503510

Weld County, CO

NENW Section 22 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: DEEPE TANK BATTERY /14N-27HZ

Location ID: 435424



Photo 1. Photo taken from the southern tank battery, facing North. Photo illustrates debris that has been dumped on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503510