

Inspection Photos

API: 071-09306

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/17/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09306 | Date: 11/17/2021

Inspection Photos



Photo 1. Facing west toward the location.



Inspection Photos



Photo 2. The vegetation is well established along the fill slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09306 | Date: 11/17/2021

Inspection Photos



Photo 3. Facing toward the pumpjack at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09306 | Date: 11/17/2021