

**RETAMCO OPERATING INC**  
**PHILADELPHIA CREEK-61S101W 28NWSE**  
**Location # 315451**



**Nearest road isn't CR 128**



**Nearest road isn't CR 128**



**RETAMCO OPERATING INC**  
**PHILADELPHIA CREEK-61S101W 28NWSE**  
**Location # 315451**



**Location covered by weeds,**



**Location covered by weeds,**



**RETAMCO OPERATING INC**  
**PHILADELPHIA CREEK-61S101W 28NWSE**  
**Location # 315451**



**Storm water washing and riling of road.**



**Storm water washing and riling of road and into location.**

**RETAMCO OPERATING INC**  
**PHILADELPHIA CREEK-61S101W 28NWSE**  
**Location # 315451**



**Washing and riling of entrance of location.**



**Erosion of edge of location.**



**RETAMCO OPERATING INC**  
**PHILADELPHIA CREEK-61S101W 28NWSE**  
**Location # 315451**



**Erosion of edge of location.**



**Erosion of edge of location.**

**RETAMCO OPERATING INC**  
**PHILADELPHIA CREEK-61S101W 28NWSE**  
**Location # 315451**



**Erosion of edge of location.**



**Storm water washing and riling of road.**



**RETAMCO OPERATING INC**  
**PHILADELPHIA CREEK-61S101W 28NWSE**  
**Location # 315451**



**Storm water washing and riling of road.**



**Storm water washing and riling of road.**

**RETAMCO OPERATING INC**  
**PHILADELPHIA CREEK-61S101W 28NWSE**  
**Location # 315451**



**Boulders on side of roadway.**



**Storm water washing and riling of road.**



**RETAMCO OPERATING INC**  
**PHILADELPHIA CREEK-61S101W 28NWSE**  
**Location # 315451**



**Low water crossing**



**Clearance is poor. Front bumper touching ground passing through low water crossing.**

**RETAMCO OPERATING INC**  
**PHILADELPHIA CREEK-61S101W 28NWSE**  
**Location # 315451**



**Low water crossing close clearance and narrow path.**

