

Interim Reclamation and Stormwater Inspection

November 16, 2021

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 461862

Inspection Document #: 697503516

Adams County, CO

NESE Section 29 T3S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Crow 3-64 29-30
Location ID: 461862



Photo 1. Google Earth aerial imagery taken 6/10/2021 illustrates the location has been built but there appears to be no evidence of drilling operations since it was constructed back in April 2019.



Inspection Photos
Location Name: Crow 3-64 29-30
Location ID: 461862



Photo 2. Photo taken from the southern location, facing North. Photo illustrates the first drilling operations are underway. Operator reported Notice of Move-in, rig-up to start on 11/15/2021.



Inspection Photos
Location Name: Crow 3-64 29-30
Location ID: 461862



Photo 3. Photo taken from the southern location, facing East. Photo illustrates Operator has maintained stormwater BMPs and appears to be performing weed management.

Note: There appears to be a soil stockpile located along the southern and western perimeter of location.



Photo 4. Photo taken from the southern location, facing West. See comments under Photo 3.

Inspection Photos
Location Name: Crow 3-64 29-30
Location ID: 461862



Photo 5. Photo taken from the western location, facing Southwest. Photo illustrates the western stockpile.



Photo 6. Photo taken from the northwestern location, facing West. Photo illustrates the retention area which has a stabilized outlet and was in proper functioning condition at the time of this inspection.

Inspection Photos
Location Name: Crow 3-64 29-30
Location ID: 461862



Photo 7. Photo taken from the northwestern location, facing North. Photo illustrates the stabilized outlet. There was no evidence of sediment discharge from location.



Photo 8. Photo taken from the northern location, facing East. See comments under Photo 3. Photo also illustrates the germination of desirable plant species with the fill slope and stormwater BMP area.