

Final Reclamation Inspection

November 11, 2021

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 311279

Inspection Document #: 697503520

Weld County, CO

NESW Section 25 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GAULKE #1
Location ID: 311279



Photo 1. Photo taken from the well location, facing West. Photo illustrates the electrical pole and debris have been removed. The well location is reflective of reference area vegetation.



Inspection Photos
Location Name: GAULKE #1
Location ID: 311279



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.



Inspection Photos
Location Name: GAULKE #1
Location ID: 311279



Photo 3. Photo taken from the well location, facing East. See comments under Photo 1.



Inspection Photos
Location Name: GAULKE #1
Location ID: 311279



Photo 4. Photo taken from the well location, facing South. See comments under Photo 1.