

Inspection Photos
Location Name: La Posta Canyon #1
API: 05-067-06121



La Posta Canyon #1 location photo. PA marker for 067-06131 in foreground.



La Posta Canyon #1 PA marker welded onto casing.

Inspection Photos
Location Name: La Posta Canyon #1
API: 05-067-06121



La Posta Canyon #1 production equipment.



Fencing being removed from around PBV prior to removal.

Inspection Photos
Location Name: La Posta Canyon #1
API: 05-067-06121



Removing soil from around the sides of the PBV.



Open topped PBV being drug out of containment area.

Inspection Photos
Location Name: La Posta Canyon #1
API: 05-067-06121



PBV removal.



Area where PBV was located.