

**Inspection Photos**  
**Location Name: Beebe-Spur 3-34 Pad**  
**Location ID: 449918**



Colorado Oil & Gas Conservation Commission  
40.45151, -104.76383, 1414.4m, 26°  
Nov 23, 2021 1:23:02 PM

**Photo 1: Wellhead Sign**



Colorado Oil & Gas Conservation Commission  
40.45151, -104.76382, 1411.7m, 37°  
Nov 23, 2021 1:23:12 PM

**Photo 2: Stained soil**




**Inspection Photos**  
**Location Name: Beebe-Spur 3-34 Pad**  
**Location ID: 449918**



Colorado Oil & Gas Conservation Commission  
40.45149, -104.76377, 1411.9m, 339°  
Nov 23, 2021 1:23:31 PM

**Photo 3: Stained soil**



Colorado Oil & Gas Conservation Commission  
40.4514, -104.76381, 1412.2m, 50°  
Nov 23, 2021 1:24:40 PM

**Photo 4: Wellhead Sign**



**Inspection Photos**  
**Location Name: Beebe-Spur 3-34 Pad**  
**Location ID: 449918**



Colorado Oil & Gas Conservation Commission  
40.45138, -104.76379, 1413.0m, 49°  
Nov 23, 2021 1:24:48 PM

**Photo 5: Stained soil**



Colorado Oil & Gas Conservation Commission  
40.45117, -104.76378, 1416.4m, 354°  
Nov 23, 2021 1:28:16 PM

**Photo 6: Stained soil**



Inspection Photos  
Location Name: Beebe-Spur 3-34 Pad  
Location ID: 449918



Photo 7: Wellhead Sign



Photo 8: Stained soil

Inspection Photos  
Location Name: Beebe-Spur 3-34 Pad  
Location ID: 449918



Colorado Oil & Gas Conservation Commission  
40.45103, -104.76382, 1413.7m, 63°  
Nov 23, 2021 1:26:10 PM

Photo 9: Wellhead Sign



Colorado Oil & Gas Conservation Commission  
40.45101, -104.76381, 1414.1m, 16°  
Nov 23, 2021 1:26:15 PM

Photo 10: Stained soil re-accumulated



**Inspection Photos**  
**Location Name: Beebe-Spur 3-34 Pad**  
**Location ID: 449918**




**Photo 11: Stained soil re-accumulated**



**Photo 12: Wellhead Sign**



**Inspection Photos**  
**Location Name: Beebe-Spur 3-34 Pad**  
**Location ID: 449918**



**Photo 13: Stained soil**



**Photo 14: Stained soil**

