

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2021

Submitted Date:

11/23/2021

Document Number:

679604314

FIELD INSPECTION FORM

Loc ID 449918	Inspector Name: Santistevan, Brittani	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10311 Name of Operator: SRC ENERGY INC Address: 1675 BROADWAY SUITE 2600 City: DENVER State: CO Zip: 80202				Findings: 30 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450250	WELL	PR	07/01/2020	OW	123-44719	Beebe 11N-26A-M	PR
450251	WELL	PR	02/01/2020	OW	123-44720	Beebe 14N-26B-M	PR
450252	WELL	PR	02/01/2020	OW	123-44721	Beebe 36N-26B-M	PR
450253	WELL	PR	10/01/2019	OW	123-44722	Beebe 25N-26B-M	PR
450254	WELL	PR	02/01/2020	OW	123-44723	Beebe 11C-26-M	PR
450255	WELL	PR	04/01/2021	OW	123-44724	Beebe 14C-26-M	PR
450256	WELL	PR	02/01/2020	OW	123-44725	Beebe 36C-26-M	PR
450257	WELL	PR	07/11/2017	OW	123-44726	Beebe 36N-26C-M	PR
450258	WELL	PR	01/15/2018	OW	123-44727	Beebe 25C-26-M	PR
450305	WELL	PR	04/01/2021	OW	123-44760	Beebe 11N-26C-M	PR
450306	WELL	PR	02/01/2020	OW	123-44761	Beebe 23N-26C-M	PR
450307	WELL	PR	12/01/2017	OW	123-44762	Beebe 23C-26-M	PR
455122	WELL	PR	11/05/2019	OW	123-46874	Beebe 36N-29B-L	PR
455123	WELL	PR	12/19/2019	OW	123-46875	Beebe 25N-29C-L	PR
455129	WELL	PR	11/10/2019	OW	123-46881	Beebe 10N-29C-L	PR
455131	WELL	PR	11/05/2019	OW	123-46883	Beebe 25N-29A-L	PR
455133	WELL	PR	11/05/2019	OW	123-46885	Beebe 36N-29A-L	PR
455135	WELL	PR	10/01/2019	OW	123-46887	Beebe 15C-29-L	PR
455136	WELL	PR	11/07/2019	OW	123-46888	Beebe 10N-29B-L	PR
455137	WELL	PR	10/01/2019	OW	123-46889	Beebe 25C-29-L	PR
455139	WELL	SI	05/01/2021	OW	123-46891	Beebe 23N-29A-L	SI
455141	WELL	PR	10/01/2019	OW	123-46893	Beebe 36C-29-L	PR

455143	WELL	PR	10/01/2019	OW	123-46895	Beebe 23C-29-L	PR
455144	WELL	PR	11/12/2019	OW	123-46896	Beebe 15N-29C-L	PR
476066	WELL	XX	04/30/2020		123-50996	Spur 07N	ND
476067	WELL	XX	04/30/2020		123-50997	Spur 34-13N-33A-M	ND
476068	WELL	XX	04/30/2020		123-50998	Spur 11C	ND
476069	WELL	XX	04/30/2020		123-50999	Spur 04N	ND
476070	WELL	XX	04/30/2020		123-51000	Spur 35-01N-3C-L	ND
476071	WELL	XX	04/30/2020		123-51001	Spur 35-02N-3A-L	ND
476072	WELL	XX	04/30/2020		123-51002	Spur 34-10C-33-M	ND
476073	WELL	XX	04/30/2020		123-51003	Spur 06N	ND
476074	WELL	XX	04/30/2020		123-51004	Spur 03N	ND
476075	WELL	XX	04/30/2020		123-51005	Spur 12N	ND
476076	WELL	XX	04/30/2020		123-51006	Spur 02N	ND
476077	WELL	XX	04/30/2020		123-51007	Spur 01NA	ND
476078	WELL	XX	04/30/2020		123-51008	Spur 10N	ND
476079	WELL	XX	04/30/2020		123-51009	Spur 08NA	ND
476080	WELL	XX	04/30/2020		123-51010	Spur 35-03C-3-L	ND
476081	WELL	XX	04/30/2020		123-51011	Spur 34-05N-33A-M	ND
476082	WELL	XX	04/30/2020		123-51012	Spur 09N	ND
476083	WELL	XX	04/30/2020		123-51013	Spur 05C	ND

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at multiple wellheads. See attached photos.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per rule 1002.(2).d.	Date:	12/23/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	#		
Comment:	31 total		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	#		
Comment:	26 total		
Corrective Action:		Date:	
Type: Bradenhead	#		
Comment:	24 total		
Corrective Action:		Date:	

Type: Compressor	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	#	
Comment:	24 total	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Pig Station	# 2	
Comment:		
Corrective Action:		Date:
Type: Vertical Separator	# 6	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 6	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2		BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity) 60 BBLS						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Base Sufficient	Adequate	
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	8	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient		Base Sufficient	Adequate	
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	450250	Type:	WELL	API Number:	123-44719	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	450251	Type:	WELL	API Number:	123-44720	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	450252	Type:	WELL	API Number:	123-44721	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	450253	Type:	WELL	API Number:	123-44722	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	450254	Type:	WELL	API Number:	123-44723	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	450255	Type:	WELL	API Number:	123-44724	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	450256	Type:	WELL	API Number:	123-44725	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	450257	Type:	WELL	API Number:	123-44726	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			

Facility ID:	450258	Type:	WELL	API Number:	123-44727	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	450305	Type:	WELL	API Number:	123-44760	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	450306	Type:	WELL	API Number:	123-44761	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	450307	Type:	WELL	API Number:	123-44762	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	455122	Type:	WELL	API Number:	123-46874	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	455123	Type:	WELL	API Number:	123-46875	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	455129	Type:	WELL	API Number:	123-46881	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			
Facility ID:	455131	Type:	WELL	API Number:	123-46883	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:									
Corrective Action:						Date:			

Facility ID: 455133	Type: WELL	API Number: 123-46885	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
Facility ID: 455135	Type: WELL	API Number: 123-46887	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
Facility ID: 455136	Type: WELL	API Number: 123-46888	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
Facility ID: 455137	Type: WELL	API Number: 123-46889	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
Facility ID: 455139	Type: WELL	API Number: 123-46891	Status: SI	Insp. Status: SI
<u>Idle Well</u>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: EQUIPMENT ONSITE				
Comment:				
Corrective Action:				Date:
Facility ID: 455141	Type: WELL	API Number: 123-46893	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
Facility ID: 455143	Type: WELL	API Number: 123-46895	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				
Corrective Action:				Date:
Facility ID: 455144	Type: WELL	API Number: 123-46896	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment:				

Corrective Action:	Date:
Facility ID: <u>476066</u>	Type: <u>WELL</u>
API Number: <u>123-50996</u>	Status: <u>XX</u>
Insp. Status: <u>ND</u>	
<u>Idle Well</u>	
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: <u>SITE CONDITION</u>
<u>Comment:</u> <u>Refer to well file for form 2</u>	
Corrective Action:	Date:
Facility ID: <u>476067</u>	Type: <u>WELL</u>
API Number: <u>123-50997</u>	Status: <u>XX</u>
Insp. Status: <u>ND</u>	
<u>Idle Well</u>	
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: <u>SITE CONDITION</u>
<u>Comment:</u> <u>Refer to well file for form 2</u>	
Corrective Action:	Date:
Facility ID: <u>476068</u>	Type: <u>WELL</u>
API Number: <u>123-50998</u>	Status: <u>XX</u>
Insp. Status: <u>ND</u>	
<u>Idle Well</u>	
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: <u>SITE CONDITION</u>
<u>Comment:</u> <u>Refer to well file for form 2</u>	
Corrective Action:	Date:
Facility ID: <u>476069</u>	Type: <u>WELL</u>
API Number: <u>123-50999</u>	Status: <u>XX</u>
Insp. Status: <u>ND</u>	
<u>Idle Well</u>	
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: <u>SITE CONDITION</u>
<u>Comment:</u> <u>Refer to well file for form 2</u>	
Corrective Action:	Date:
Facility ID: <u>476070</u>	Type: <u>WELL</u>
API Number: <u>123-51000</u>	Status: <u>XX</u>
Insp. Status: <u>ND</u>	
<u>Idle Well</u>	
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: <u>SITE CONDITION</u>
<u>Comment:</u> <u>Refer to well file for form 2</u>	
Corrective Action:	Date:
Facility ID: <u>476071</u>	Type: <u>WELL</u>
API Number: <u>123-51001</u>	Status: <u>XX</u>
Insp. Status: <u>ND</u>	
<u>Idle Well</u>	
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: <u>SITE CONDITION</u>
<u>Comment:</u> <u>Refer to well file for form 2</u>	
Corrective Action:	Date:
Facility ID: <u>476072</u>	Type: <u>WELL</u>
API Number: <u>123-51002</u>	Status: <u>XX</u>
Insp. Status: <u>ND</u>	

Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<input type="text" value="Refer to well file for form 2"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Facility ID:	476073	Type:	WELL	API Number: 123-51003 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<input type="text" value="Refer to well file for form 2"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Facility ID:	476074	Type:	WELL	API Number: 123-51004 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<input type="text" value="Refer to well file for form 2"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Facility ID:	476075	Type:	WELL	API Number: 123-51005 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<input type="text" value="Refer to well file for form 2"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Facility ID:	476076	Type:	WELL	API Number: 123-51006 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<input type="text" value="Refer to well file for form 2"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Facility ID:	476077	Type:	WELL	API Number: 123-51007 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION	
Comment:	<input type="text" value="Refer to well file for form 2"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Facility ID:	476078	Type:	WELL	API Number: 123-51008 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: [Refer to well file for form 2](#)

Corrective Action:

Date:

Facility ID: 476079 Type: WELL API Number: 123-51009 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: [Refer to well file for form 2](#)

Corrective Action:

Date:

Facility ID: 476080 Type: WELL API Number: 123-51010 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: [Refer to well file for form 2](#)

Corrective Action:

Date:

Facility ID: 476081 Type: WELL API Number: 123-51011 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: [Refer to well file for form 2](#)

Corrective Action:

Date:

Facility ID: 476082 Type: WELL API Number: 123-51012 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: [Refer to well file for form 2](#)

Corrective Action:

Date:

Facility ID: 476083 Type: WELL API Number: 123-51013 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: [Refer to well file for form 2](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679603983. All previous corrective actions assigned in previous inspection have been resolved. One new corrective action has been observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary **Weather Conditions: cloudy, dry ground On Tuesday, November 23, 2021 at approximately 13:45, I, Inspector Brittani Santistevan, conducted an on-site inspection at BEEBE-SPUR 3-34 PAD (PDC Energy), at location #: 449918 in WELD COUNTY, Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. It appears multiple wellheads have stained soil surrounding the casing. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d. (Corrective Action Date: December 23, 2021) See attached photo #1-14.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	11/23/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604315	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5588616