

Inspection Photos  
Location Name: UPRR 42 Pan Am D2  
Location ID: 318931



Photo 1 WH sign

Photo 2 WH

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am D2**  
**Location ID: 318931**



**Photo 3 Pump Jack**

**Photo 4 ancillary equipment**

Inspection Photos  
Location Name: UPRR 42 Pan Am D2  
Location ID: 318931



Photo 5 TB sign

Photo 6 TB

# Inspection Photos

Location Name: UPRR 42 Pan Am D2

Location ID: 318931



**Photo 7 stained soil on east side of crude tank**

**Photo 8 Gas Meter Run**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am D2**  
**Location ID: 318931**



**Photo 9 Horiz. Heated Sep.**