

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36NESW

Location ID: 335145



Photo #5222 from entrance to location.



Photo #5223 from entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36NESW

Location ID: 335145



Photo #5224 Wellhead sign weathered and not legible.



Photo #4562 from inspection #699803446 inspection conducted on 7/22/21.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36NESW

Location ID: 335145



Photo #5225 No battery sign located at the tank battery.



Photo #4559 from inspection #699803446 inspection conducted on 7/22/21.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36NESW

Location ID: 335145



**Photo #5226 Location lacks stabilization.**



**Photo #4560 from inspection #699803446 inspection conducted on 7/22/21.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36NESW

Location ID: 335145



**Photo #5227 Insufficient tracking BMP located at entrance to location.**