


**Inspection Photos**  
**Location Name: Dunn 1-13H**  
**Location ID: 426458**



**Photo 1 – Tank Battery – North Tank – Capacity Labels**



**Photo 2 – Produced Water Tank – Capacity Labels**



**Inspection Photos**  
**Location Name: Dunn 1-13H**  
**Location ID: 426458**



**Photo 3 – Tank Battery Sign**



**Photo 4 – Heater Treater**





**Inspection Photos**  
**Location Name: Dunn 1-13H**  
**Location ID: 426458**



**Photo 5 – Wellhead**



**Photo 6 – Chemical Label – Faded**