

Inspection Photos

Location Name: BERRY PETROLEUM COMPANY LLC CHEVRON K17 696 /

Location ID: 335596



Photo #5265 from entrance to location.



Photo #5266 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: BERRY PETROLEUM COMPANY LLC CHEVRON K17 696 /

Location ID:



Photo #5267 Debris by wellheads.



Photo #5268 Debris by wellheads.

Inspection Photos

Location Name: BERRY PETROLEUM COMPANY LLC CHEVRON K17 696 /

Location ID:



Photo #5269 Location lack stabilization.




Photo #5270 Location lacks stabilization.

Inspection Photos

Location Name: BERRY PETROLEUM COMPANY LLC CHEVRON K17 696 /

Location ID:



Photo #5271 No form of tracking BMP located at the entrance to location.