

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CSOC 696-18-66S96W /17NESW

Location ID: 335793



Photo #5272 from entrance to location.



Photo #5273 from entrance to location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: CAERUS PICEANCE LLC CSOC 696-18-66S96W /17NESW

Location ID: 335793



**Photo #5274 Condensate tanks missing required information.**



**Photo #5275 Multiple wellhead sign weathered and not legible.**