

Final Reclamation Inspection

November 16, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 319236

Inspection Document #: 697503524

Weld County, CO

CNW Section 22 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CARL R. DEEPE #2
Location ID: 319236



Photo 1. Photo taken from the eastern well location access road, facing West. Photo illustrates the access is evident and needs to be reclaimed per Rule 1004 standards.

Inspection Photos
Location Name: CARL R. DEEPE #2
Location ID: 319236



Photo 2. Photo taken from the well location, facing Northwest. Photo illustrates the evidence of desirable plant species; however, the well location will remain in-process.



Photo 3. Photo taken from the well location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: CARL R. DEEPE #2
Location ID: 319236



Photo 4. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: CARL R. DEEPE #2
Location ID: 319236



Photo 5. Photo taken from the associated offsite tank battery, facing North. The associated offsite tank battery has been removed and replaced with a new production facility for other nearby active wells. Note: A corrective action has been submitted to remove the debris pile.