

Inspection Photos
Location Name: Bulldog 20-12H-892
Location ID: 429116



Photo 1. Overview of location taken facing northwest. Dried weeds on location. Rills visible on cut slope.

