

**Inspection Photos**  
**Location Name: San Isabel S1**  
**Location ID:322262**



**Photo 1 Loc pic**



**Photo 2 Stained soil around well head and under PU**

**Inspection Photos**  
**Location Name: San Isabel S1**  
**Location ID:322262**



**Photo 3 stained soil around crude oil load out line .**



**Photo 4 Unused equipment belt guard and stained soil under PU base.**