

Inspection Photos

Location Name: UPRR 42 PAN AM AV 1

Location ID: 323102

Nov 29, 2021 at 1:34:05 PM
40.063408,-104.940067
015 Colorado Blvd
Dacono CO 80514
United States
COGCC



Pic 1 wellhead / weeds unmanaged

Nov 29, 2021 at 1:34:09 PM
40.063408,-104.940067
015 Colorado Blvd
Dacono CO 80514
United States
COGCC



Pic 2 Unused equipment / weeds unmanaged



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: UPRR 42 PAN AM AV 1

Location ID: 323102

Nov 29, 2021 at 1:34:25 PM
40.063408,-104.940067
015 Colorado Blvd
Dacono CO 80514
United States
COGCC



Pic 3 unused equipment

Nov 29, 2021 at 1:35:33 PM
40.063395,-104.939912
015 Colorado Blvd
Dacono CO 80514
United States
COGCC



Pic 4 stained soil by tank that is on location.