

Inspection Photos
Location Name: Chaney #1-1
Location ID: 326264



Photo 1 Debris Dead weeds along road access

Photo 2 Well sign. Debris: Dead weeds along location

Inspection Photos
Location Name: Chaney #1-1
Location ID: 326264



Colorado Oil and Gas Conservation Commission
37.23173, -107.80079, 2108.0m
Dec 7, 2021 10:49:09 AM



Colorado Oil and Gas Conservation Commission
37.2319, -107.80084, 2107.0m
Dec 7, 2021 10:49:47 AM

Photo 3 Debris: Dead weeds on location

Photo 4 Stained soil from exhaust and motor

Inspection Photos
Location Name: Chaney #1-1
Location ID: 326264



Photo 5 Trash: Wind wall material in disrepair laying on ground.

Photo 6 WH

Inspection Photos
Location Name: Chaney #1-1
Location ID: 326264



Colorado Oil and Gas Conservation Commission
37.23217, -107.80065, 2110.0m
Dec 7, 2021 10:50:46 AM

Photo 7 Vert Sep and meter house



Colorado Oil and Gas Conservation Commission
37.23224, -107.80066, 2110.0m
Dec 7, 2021 10:50:57 AM

Photo 8 production tank

Inspection Photos
Location Name: Chaney #1-1
Location ID: 326264



Photo 9 Debris: dead weeds on location.

Photo 10 Dead weeds on location.