

# Inspection Photos

API: 071-08637

Operator: OGRIS OPERATING LLC

Inspection Date: 12/8/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08637 | Date: 12/8/2021

## Inspection Photos



**Photo 1.** Facing southwest along the access road. There is water draining down the road which needs to be properly diverted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08637 | Date: 12/8/2021

## Inspection Photos



**Photo 2.** Standing at the well site facing north toward the road. The source of the water flowing down the road is unknown and should be inspected by the operator.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08637 | Date: 12/8/2021

## Inspection Photos



**Photo 3.** Facing toward the well site.



## Inspection Photos



**Photo 4.** Further down the canyon at the compressor station. There is an area of stained soil that needs to be cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08637 | Date: 12/8/2021