

Inspection Photos

12/07/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335045

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335045



December 7, 2021
39.43598038N 107.8283996W



December 7, 2021
39.43598523N 107.82840317W

Photo 1: Photos taken from the east end of the Location. Photos show that though work to address the compliance issues is in process at time of inspection, control measures to stabilize the production areas and to mitigate tracking and offsite sediment transport remain missing or insufficient. Operator on site observed re-grading tracking/ruts on the production areas; re-grading alone insufficient to address stabilization, tracking and offsite sediment transport.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335045



Photo 2: Photos taken from the east end of the Location. Photos show that though work to address the compliance issues is in process at time of inspection, control measures to stabilize the production areas and to mitigate tracking and offsite sediment transport remain missing or insufficient. Operator on site observed re-grading tracking/ruts on the production areas; re-grading alone insufficient to address stabilization, tracking and offsite sediment transport.