

**Inspection Photos**  
**Location Name: MC Williams 2-31**  
**Location ID: 312949**



**Photo 1. Overview of location taken facing north.**



**Inspection Photos**  
**Location Name: MC Williams 2-31**  
**Location ID: 312949**



**Photo 2. No bradenhead access apparent. Wellhead sign knocked over.**



**Photo 3. Dried annual weeds have become debris.**