

Inspection Photos
Location Name: McWilliams 4-31
Location ID: 312982



Photo 1. Overview of location taken facing southwest.



Inspection Photos
Location Name: McWilliams 4-31
Location ID: 312982



Photo 2. Wellhead sign knocked over.



Photo 3. No bradenhead access apparent.