

Inspection Photos
Location Name: State Antelope 34-12 PAD
Location ID: 431418



Colorado Oil and Gas Conservation Commission
40.40818, -104.26776, 4578.0ft, 259°
12/06/2021 14:08:54



Colorado Oil and Gas Conservation Commission
40.40877, -104.26966, 4549.5ft, 269°
12/06/2021 14:09:36

Photo 1 – Signs at Entrance

Photo 2 – Wellheads

Inspection Photos
Location Name: State Antelope 34-12 PAD
Location ID: 431418



Colorado Oil and Gas Conservation Commission
40.40914, -104.26886, 4546.9ft, 196°
12/06/2021 14:10:15



Colorado Oil and Gas Conservation Commission
40.4093, -104.26881, 4539.2ft, 218°
12/06/2021 14:22:16

Photo 3 – 34-12 and 44-41 Wellheads – Missing Wellhead Signs

Photo 4 – Separators

Inspection Photos
Location Name: State Antelope 34-12 PAD
Location ID: 431418



Photo 5 – Gas Meter Shed – WEEDS

Photo 6 – WEEDS

Inspection Photos
Location Name: State Antelope 34-12 PAD
Location ID: 431418



Photo 7 – Tank Battery



Photo 8 – WEEDS and Unused Pipe

Inspection Photos
Location Name: State Antelope 34-12 PAD
Location ID: 431418



Photo 9 – Unused Secondary Containment