

Inspection Photos
Location Name: Antelope 42-31 PAD
Location ID: 421167




Photo 1 – Q-31 Wellhead – Unmarked Risers

Photo 2 – 42-31 Wellhead – Unmarked Risers

Inspection Photos
Location Name: Antelope 42-31 PAD
Location ID: 421167



Photo 3 – 32-31 Wellhead – Unmarked Risers




Photo 4 – Unmarked Risers

Inspection Photos
Location Name: Antelope 42-31 PAD
Location ID: 421167



Photo 5 – 41-44-31HZ Separator

Photo 6 – Unmarked Risers

Inspection Photos
Location Name: Antelope 42-31 PAD
Location ID: 421167



Colorado Oil and Gas Conservation Commission
40.35783, -104.35929, 4511.8ft, 167°
12/07/2021 14:48:05

Photo 7 – Unmarked Riser



Colorado Oil and Gas Conservation Commission
40.35783, -104.35939, 4523.6ft, 240°
12/07/2021 14:48:18

Photo 8 – 41-44-31HZ Tank Battery (East Side) – Water Tank:
Capacity Label. North Oil: Content and Capacity

Inspection Photos
Location Name: Antelope 42-31 PAD
Location ID: 421167




Photo 9 – 41-44-31HZ Tank Battery (East Side) – Unmarked Risers

Photo 10 – West Side Tank Battery

Inspection Photos
Location Name: Antelope 42-31 PAD
Location ID: 421167



Colorado Oil and Gas Conservation Commission
40.35793, -104.3601, 4526.8ft, 185°
12/07/2021 14:50:46



Colorado Oil and Gas Conservation Commission
40.35797, -104.36011, 4522.1ft, 4°
12/07/2021 14:50:54

Photo 11 – West Side Tank Battery – Unmarked Risers

Photo 12 – West Side Separators

Inspection Photos
Location Name: Antelope 42-31 PAD
Location ID: 421167



Photo 13 – West Side Tank Battery Signs

Photo 14 – West Side Separators – Unmarked Riser

Inspection Photos
Location Name: Antelope 42-31 PAD
Location ID: 421167



Photo 15 – West Side Separators – Unmarked Riser