

Tank repaired and thief hatch closed after spill clean up



Chemical injection system put back into service after spill clean up.

