

Attachment B



WELLHEAD ABANDONMENT FORM

SITE NAME: L&T 22-15 Wellhead							DATE: 9/15/2021	REM. PROJECT #: 18520	WEATHER: Sunny			
SITE DIRECTIONS: HWY 34 & HWY 257, S 0.9 To 29th St. W 0.5, S into							CLIENT: PDC/ Delbert Pace					
LEGALS AND LAT/LONG: 40.388790 -104.873620							TASMAN PERSONNEL: Dylan Brightwell					
SOIL TYPES: Silty Sand - SM							SURFACE GRADIENT: South					
SOIL SAMPLING							FACILITY INFRASTRUCTURE					
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity			
							Above Ground Storage Tank (AST)					
9/15/2021 09:50	WH01 @6'	0.1	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel					
9/15/2021 09:52	FLR01 @4'	0.0	No Staining	No Odor	Yes	Lab	Separator					
9/15/2021 10:16	WHS01-N @0-6"	0.0	No Staining	No Odor	Yes	Grab	Emission Control Device (ECD)					
9/15/2021 10:18	WHS01-W @0-6"	0.0	No Staining	No Odor	Yes	Grab	Dump Line					
9/15/2021 10:20	WHS01-S @0-6"	0.0	No Staining	No Odor	Yes	Grab	Wellhead		1			
9/15/2021 10:22	WHS01-E @0-6"	0.0	No Staining	No Odor	Yes	Grab	Flowline		1			
9/15/2021 10:30	FL01-01@4'	0.0	No Staining	No Odor	Yes	Grab	Other:					
9/15/2021 10:32	FL01-02 @4'	0.1	No Staining	No Odor	Yes	Grab	Soil Loads Removed					
9/15/2021 10:34	FL01-03@4'	0.0	No Staining	No Odor	Yes	Grab	IMPACTED SOIL IDENTIFIED?					
9/15/2021 10:36	FL01-04@4'	0.0	No Staining	No Odor	Yes	Grab	ESTIMATED VOLUME OF IMPACTS:					
9/15/2021 10:38	FL01-05@4'	0.0	No Staining	No Odor	Yes	Grab	Date	Number	CY			
9/15/2021 10:46	BKG01 @4'	0.0	No Staining	No Odor	Yes	Lab						
9/15/2021 10:50	BKG01 @6'	0.1	No Staining	No Odor	Yes	Lab						
9/16/2021 10:38	FL01-06 @4'	0.0	No Staining	No Odor	Yes	Grab						
9/16/2021 10:42	FL01-07 @4'	0.0	No Staining	No Odor	Yes	Grab						
9/16/2021 11:34	FL01-08 @4'	0.0	No Staining	No Odor	Yes	Grab	Total Removed		0	0		
							Disposal Facility:					
							Groundwater Recovery					
							DATE GW ENCOUNTERED:			DEPTH:		
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?					
							LNAPL OR SHEEN OBSERVED ON GW?					
GROUNDWATER SAMPLING							Date		BBLs			
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?						
							Total Removed		0			
							Disposal Facility:					

Photographic Log

					
Equipment ID: WH01@6'		Equipment Type:	Equipment ID: FLR01@4'		Equipment Type:
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Soil sample collected next to cut and capped L&T 22-15 wellhead			Notes/Conditions: Soil sample collected under elbow of flowline riser at L&T 22-15 wellhead		

Photographic Log

					
Equipment ID: WH01		Equipment Type:	Equipment ID: WHS01-N@0-6"		Equipment Type:
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Cut and capped L&T 22-15 wellhead.			Notes/Conditions: Surface sample collected on the North side of L&T 22-15 wellhead.		

Photographic Log



Equipment ID: WHS01-W@0-6"			Equipment Type:			Equipment ID: WHS01-S@0-6"			Equipment Type:					
Material:			Volume:			Material:			Volume:			Contents:		
Notes/Conditions: Surface sample collected on the West side of L&T 22-15 wellhead.						Notes/Conditions: Surface sample collected on the South side of L&T 22-15 wellhead.								

Photographic Log

					
Equipment ID: WHS01-E@0-6"		Equipment Type:	Equipment ID: FL01-01@4'		Equipment Type:
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Surface sample collected on the East side of L&T 22-15 wellhead.			Notes/Conditions: Soil sample collected beside flowline and field screened.		

Photographic Log

					
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Soil sample collected beside flowline and field screened.			Notes/Conditions: Soil sample collected beside flowline and field screened.		

Photographic Log



Equipment ID: FL01-04@4'		Equipment Type:		Equipment ID: FL01-05@4'		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions: Soil sample collected beside flowline and field screened.				Notes/Conditions: Soil sample collected using hand auger alongside the flowline and field screened.			

Photographic Log

					
<p>Equipment Type:</p>			<p>Equipment ID:FL01-06@4'</p> <p>Material:</p> <p>Volume:</p> <p>Contents:</p> <p>Notes/Conditions: Soil sample collected using hand auger alongside the flowline and field screened.</p>		

Photographic Log

					
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: Soil sample collected using hand auger alongside the flowline and field screened.			Notes/Conditions: Soil sample collected under the elbow of the flowline next to the separator.		