

Interim Reclamation and Stormwater Inspection

December 14, 2021

Operator: VERDAD RESOURCES LLC #10651

Location ID: 457136

Inspection Document #: 697503572

Weld County, CO

NWSE Section 14 T9N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rohn 9-60 /14A
Location ID: 457136



Photo 1. 2019 aerial imagery illustrates the location prior to interim reclamation activities.

Inspection Photos
Location Name: Rohn 9-60 /14A
Location ID: 457136



Photo 2. Photo taken from the eastern well pad, facing Southwest. Photo illustrates Operator has performed interim reclamation activities to reduce all areas only needed for production operations.



Photo 3. Photo taken from the eastern well pad, facing Northwest.



Photo 4. Photo taken from a portion of the interim reclamation area. Photo illustrates no germination of desirable vegetation. Interim reclamation areas consist mostly of Kochia and Russian thistle. Note- Operator is managing weeds and mowing operations have been performed.

Inspection Photos
Location Name: Rohn 9-60 /14A
Location ID: 457136



Photo 5. Photo taken from the eastern interim reclamation area, facing North. See comments under Photo 4.



Photo 6. Photo taken from the eastern interim reclamation area, facing East. See comments under Photo 4.

Inspection Photos
Location Name: Rohn 9-60 /14A
Location ID: 457136



Photo 7. Photo taken from the eastern interim reclamation area, facing Southwest. See comments under Photo 4.



Photo 8. Photo taken from the southeastern interim reclamation area, facing Southeast. See comments under Photo 4.

Inspection Photos
Location Name: Rohn 9-60 /14A
Location ID: 457136



Photo 9. Reference photo taken from an undisturbed portion along the southeastern interim area. Photo illustrates mostly blue grama with some buffalo grass, green needlegrass and western wheatgrass.

Inspection Photos
Location Name: Rohn 9-60 /14A
Location ID: 457136



Photo 10. Close up reference photo. See comments under Photo 9.