

Final Reclamation Inspection

November 10th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 326994

Inspection Document #: 701900253

Weld County, CO

NESE Section 16 T6N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State Lease 81 43-16
Location ID: 326994



Photo 1. 2013 (left) vs 2029 (right) aerial imagery of the well pad. Photos show weeds in close proximity to the PA'd well (see photo 2). Note: The Tank Battery to the west is not associated with this inspection and remains for the TA well (123-20595) not pictured to the south.

Inspection Photos
Location Name: State Lease 81 43-16
Location ID: 326994



Photo 2. Overview photo of the reclaimed well taken at ground level from the southern edge looking north.

Inspection Photos
Location Name: State Lease 81 43-16
Location ID: 326994



Photo 3. Large patch of field bindweed in southeastern corner of the tank battery. In close proximity to reclaimed well pad.