

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2021

Submitted Date:

12/17/2021

Document Number:

700600346

FIELD INSPECTION FORMLoc ID 470688 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 95620

Name of Operator: WESTERN OPERATING COMPANY

Address: 1165 DELAWARE STREET #200

City: DENVER State: CO Zip: 80204

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Dale	719-688-1638	dale@westernoperating.com	
James, Steven D	(303) 893-2438	steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480894	SPILL OR RELEASE	AC	10/11/2021		-	King Pyles #4	EI

General Comment:

This is an environmental inspection to document status of spill 480894 clean up.

Form 19 must be submitted to close spill no later than 1/4/2022. If spill clean up is not completed by 1/4/2022 then operator shall submit Form 27 remediation plan to area Environmental Protection Specialist for approval prior to 1/4/2022.

Excavation of impacted soil was occurring at the time of inspection (see attached photos).

Environmental**Spills/Releases:**

Type of Spill: OIL _____

Estimated Spill Volume: _____

Comment: Form 19 to close spill must be submitted no later than 1/4/2022.

Corrective Action: If spill cleanup cannot be completed and documented by 1/4/2022 then operator shall submit a Form 27 Remediation Plan to Area EPS for approval by 1/4/2022.

Date: 01/04/2022

Reportable: YES _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700600347	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5610717