

100

Location FEDERAL 10-7-101 #13 Date 15 OCT 2011
 Project / Client PIT SAMPLING / MERRION
CWJFE. OVERCAST ~ 60%

1240 - ONSITE.

LINER IN PIT WAS TORN BEFORE ARRIVAL
 ON SITE. LINER REMOVED BY BACK HOE

BACKGROUND SAMPLES COLLECTED OFF WELL PAD
 ~ 50-100' FROM PIT LOCATION AT 4
 LOCATIONS N, S, E & W OF WELL PAD

| SAMPLE | DEPTH | TIME | DESC | STRONG |
|----------|--------|------|-----------------------------------|--------|
| PB01 | 22' | 1256 | BLACK STAINING, ODOOR | |
| BC01 (N) | 1 1/2" | 1245 | SLIGHTLY DARK, SLIGHT ODOOR | |
| BC02 (S) | 6" | 1256 | NO STAIN, NO ODOOR | |
| BC03 (E) | 6" | 1302 | DARK SOIL, CLUMPY, NO ODOOR | |
| BC04 (W) | 6" | 1310 | SANDY CLUMP, NO ODOOR NO STAIN | |

ALL SAMPLES PLACED ON ICE IN COOLER.

WORK CREW WILL REMOVE LINER WITH A TRAILER
 AND TAKE TO DISPOSAL.

1315 - OFF SITE

Chris Wilson
 15 OCT 2011

101

Doc # 1313069

REM # 8405

Pit 272878

