

Inspection Photos

API: 071-09508

Operator: OGRIS OPERATING LLC

Inspection Date: 12/16/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09508 | Date: 12/16/2021

Inspection Photos



Photo 1. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09508 | Date: 12/16/2021

Inspection Photos



Photo 2. The vegetation is well established along the fill slope of the location.



Inspection Photos



Photo 3. The electric fence around the pit is in disrepair and needs to be fixed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09508 | Date: 12/16/2021

Inspection Photos



Photo 4. The solar panels at the meter shed have blown over.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09508 | Date: 12/16/2021