

Inspection Photos
Location Name: State Antelope P-16 PAD
Location ID: 432999



Photo 1 – Pumping Units

Photo 2 – Wellheads

Inspection Photos
Location Name: State Antelope P-16 PAD
Location ID: 432999



Photo 3 – West Tanks – NFPA Labels

Photo 4 – Tank Battery

Inspection Photos
Location Name: State Antelope P-16 PAD
Location ID: 432999



Photo 5 – 1” Riser at Tanks

Photo 6 – Separators

Inspection Photos
Location Name: State Antelope P-16 PAD
Location ID: 432999



Photo 7 – Unmarked Risers