

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 1 – Tank Battery Signs

Photo 2 – Wellheads



Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 3 – Pumping Unit



Photo 4 – Unmarked Riser at Pumping Unit Wellhead

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 5 – NFA Label



Photo 6 – Unused Containment

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 7 – Tank Battery



Photo 8 – Unmarked 1" Riser



Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 9 – Separators




Photo 10 – Unmarked 2" Riser



Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 11 – Unmarked Riser



Photo 12 – ECDs and Gas Meter House

Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 13 – Compressor




Photo 14 – Tags weathered off



Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 15 – Labels have faded



Photo 16 – Day Tank Netting



Inspection Photos
Location Name: Antelope P-17 PAD
Location ID: 428964



Photo 17 – Signs at Entrance

