

**Inspection Photos**  
**Location Name: Antelope P-21 PAD**  
**Location ID: 404901**



**Photo 1 – Wellheads – Unmarked Risers**



**Photo 2 – Wellheads – Unmarked Risers**



**Inspection Photos**  
**Location Name: Antelope P-21 PAD**  
**Location ID: 404901**



**Photo 3 – Unmarked Riser at Wellheads**



**Photo 4 – ECD**



**Inspection Photos**  
**Location Name: Antelope P-21 PAD**  
**Location ID: 404901**



**Photo 5 – Separators**



**Photo 6 – Unmarked Riser**

# Inspection Photos

Location Name: Antelope P-21 PAD  
Location ID: 404901



Photo 7 – Tank Battery




Photo 8 – East Tanks – Content and Capacity

**Inspection Photos**  
**Location Name: Antelope P-21 PAD**  
**Location ID: 404901**



**Photo 9 – Tank Battery Signs**



**Photo 10 – East Tanks – Content and Capacity**





**Inspection Photos**  
**Location Name: Antelope P-17 PAD**  
**Location ID: 428964**



**Photo 11 – Unmarked Risers at Separators**