

Inspection Photos  
Operator: Simcoe  
API: 067-07556  
Date: 12/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with crested wheatgrass, intermediate wheatgrass. Approximately 300 Scotch thistles observed within the interim reclamation areas.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with gambel oak, mountain mahogany, sagebrush, Indian ricegrass, blue grama, James galleta, and penstemon.