

**Inspection Photos**  
**Location Name: Herbst 22-614**  
**Location ID: 330242**



**Photo #1 Well & Removed Stained Soil**



**Photo #2 Appears to be Mechanical Conditions on the Packing Injection Fitting on the master valve.**