

**FORM  
INSP**Rev  
X/20

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/14/2021

Submitted Date:

12/14/2021

Document Number:

696303849

**FIELD INSPECTION FORM**
 Loc ID 421208 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

19 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email                     | Comment         |
|----------------|-------|---------------------------|-----------------|
| ,              |       | EHSRC@bonanzacrk.com      | All Inspections |
| Pesicka, Conor |       | conor.pesicka@state.co.us |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 421203      | WELL | PR     | 08/01/2021  | GW         | 123-32841 | Antelope S-31  | PR          |
| 421303      | WELL | TA     | 10/05/2020  | GW         | 123-32876 | Antelope 24-31 | TA          |
| 421308      | WELL | SI     | 08/01/2021  | GW         | 123-32878 | Antelope 13-31 | SI          |
| 421309      | WELL | PR     | 08/01/2021  | GW         | 123-32879 | Antelope 23-31 | PR          |
| 421313      | WELL | TA     | 10/05/2020  | GW         | 123-32882 | Antelope 34-31 | TA          |
| 421320      | WELL | TA     | 04/25/2019  | GW         | 123-32885 | Antelope 33-31 | TA          |
| 421331      | WELL | TA     | 10/07/2019  | GW         | 123-32889 | Antelope 43-31 | TA          |
| 421332      | WELL | TA     | 10/07/2019  | GW         | 123-32890 | Antelope 44-31 | TA          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | BATTERY              |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | Adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | UNUSED EQUIPMENT                                   |       |            |
| Comment:           | Unmarked Risers at Tanks and Wellheads; see photos |       |            |
| Corrective Action: | Comply with Rule 606                               | Date: | 12/17/2021 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |             |       |  |
|--------------------|-------------|-------|--|
| Type               | LOCATION    |       |  |
| Comment:           | Barbed Wire |       |  |
| Corrective Action: |             | Date: |  |
| Type               | WELLHEAD    |       |  |
| Comment:           | Panels      |       |  |
| Corrective Action: |             | Date: |  |

**Equipment:**

|                     |                                 |       |                 |
|---------------------|---------------------------------|-------|-----------------|
|                     |                                 |       | corrective date |
| Type: Gas Meter Run | # 3                             |       |                 |
| Comment:            |                                 |       |                 |
| Corrective Action:  |                                 | Date: |                 |
| Type: Bradenhead    | # 7                             |       |                 |
| Comment:            | Appear to be plumbed to surface |       |                 |
| Corrective Action:  |                                 | Date: |                 |

|                                   |              |  |       |
|-----------------------------------|--------------|--|-------|
| Type: Plunger Lift                | # 3          |  |       |
| Comment:                          |              |  |       |
| Corrective Action:                |              |  | Date: |
| Type: Other                       | # 4          |  |       |
| Comment:                          | TA Wellheads |  |       |
| Corrective Action:                |              |  | Date: |
| Type: Emission Control Device     | # 1          |  |       |
| Comment:                          |              |  |       |
| Corrective Action:                |              |  | Date: |
| Type: Horizontal Heated Separator | # 3          |  |       |
| Comment:                          |              |  |       |
| Corrective Action:                |              |  | Date: |

**Tanks and Berms:**

| Contents           | # | Capacity | Type        | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER     | 2 | OTHER    | BV CONCRETE |         | ,      |
| Comment:           |   |          |             |         |        |
| Corrective Action: |   |          |             |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 60 BBLS  |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                         | Permeability (Wall) | Permeability (Base) | Maintenance |                       |
|--------------------|----------------------------------|---------------------|---------------------|-------------|-----------------------|
|                    |                                  |                     |                     |             |                       |
| Comment:           | Shares berm with Crude Oil Tanks |                     |                     |             |                       |
| Corrective Action: |                                  |                     |                     | Date:       |                       |
| Contents           | #                                | Capacity            | Type                | Tank ID     | SE GPS                |
| CRUDE OIL          | 4                                | 400 BBLS            | STEEL AST           |             | 40.352970,-104.361680 |
| Comment:           |                                  |                     |                     |             |                       |
| Corrective Action: |                                  |                     |                     |             |                       |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type     | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|----------|---------------------|---------------------|-------------|
| Metal    | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment: |          |                     |                     |             |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|  |  |  |
|--|--|--|
|  |  |  |
|--|--|--|

**Inspected Facilities**

Facility ID: 421203 Type: WELL API Number: 123-32841 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 421303 Type: WELL API Number: 123-32876 Status: TA Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: TA MIT: 09.30.2020

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 421308 Type: WELL API Number: 123-32878 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI - This Well is on another PAD - Antelope G-31 PAD Location ID - 421200

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 421309 Type: WELL API Number: 123-32879 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 421313 Type: WELL API Number: 123-32882 Status: TA Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: TA - MIT: 09.30.2020

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 421320 Type: WELL API Number: 123-32885 Status: TA Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: TA - MIT: 04.09.2021

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 421331 Type: WELL API Number: 123-32889 Status: TA Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [TA - MIT: 07.08.2021](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 421332 Type: WELL API Number: 123-32890 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [TA - MIT: 04.22.2021](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <a href="#">Routine Field Inspection. Unmarked Risers at Tanks and Wellheads.</a> | petrie | 12/14/2021 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402899498    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607718">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607718</a> |
| 696303850    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607711">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607711</a> |