

Inspection Photos
Location Name: Antelope 13-17 PAD
Location ID: 420920




Photo 1 – Wellhead – Unmarked Riser and Unused Lubricator Body




Photo 2 – Wellheads – Unmarked Risers



Inspection Photos
Location Name: Antelope 13-17 PAD
Location ID: 420920




Photo 3 – Tank Battery – Content and Capacity Labels



Photo 4 – Tank Battery

Inspection Photos
Location Name: Antelope 13-17 PAD
Location ID: 420920



Photo 5 – Tank Battery – Content and Capacity Labels



Photo 6 – Tank Battery Signs



Inspection Photos
Location Name: Antelope 13-17 PAD
Location ID: 420920



Photo 7 – Separators