

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-66S96W /35SWSW

Location ID: 324121



Photo #5471 from entrance to location.



Photo #5474 Storage tank not labeled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-66S96W /35SWSW

Location ID: 324121



Photo #5475 Sight glass indicates the storage tank is full of an unknown fluid.



Photo #5476 Storage tank is located under horizontal separator.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-66S96W /35SWSW

Location ID: 324121



Photo #5477 Location lacks stabilization.



Photo #5478 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-66S96W /35SWSW

Location ID: 324121



Photo #5479 Insufficient tracking BMP located at entrance to location.

