

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /35SESW

Location ID: 334595



Photo #5480 from entrance to location.



Photo #5481 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /35SESW

Location ID: 334595




Photo #5482 Storage tank not labeled.




Photo #5483 Sight glass indicates the storage tank is full of an unknown fluid.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /35SESW

Location ID: 334595



Photo #5484 Storage tank located under horizontal separator.