

Inspection Photos  
Location Name: Castor 8-59-19 PAD  
Location ID: 452871



Photo 1 – Wellhead





Photo 2 – Wellhead

**Inspection Photos**  
**Location Name: Castor 8-59-19 PAD**  
**Location ID: 452871**



**Photo 3 – Wellheads**



**Photo 4 – 8-59-19-24-3 Wellhead – Sign missing**



**Inspection Photos**  
**Location Name: Castor 8-59-19 PAD**  
**Location ID: 452871**



**Photo 5 – Chemical Tank missing Label**



**Photo 6 – Gas Injection Meter Shed**



**Inspection Photos**  
**Location Name: Castor 8-59-19 PAD**  
**Location ID: 452871**



**Photo 7 – Separators**



**Photo 8 – Compressor Drain Vault now has Signage**





**Inspection Photos**  
**Location Name: Castor 8-59-19 PAD**  
**Location ID: 452871**



**Photo 9 – Separators**



**Photo 10 – LACT**



**Inspection Photos**  
**Location Name: Castor 8-59-19 PAD**  
**Location ID: 452871**



**Photo 11 – Tanks**



**Photo 12 – Tanks and VRT moved for Clean-Up**



**Inspection Photos**  
**Location Name: Castor 8-59-19 PAD**  
**Location ID: 452871**



**Photo 13 – Tanks and ECDs**



**Photo 14 – Day Tank Netting in disrepair**

**Inspection Photos**  
**Location Name: Castor 8-59-19 PAD**  
**Location ID: 452871**



**Photo 15 – Tanks and ECDs**



**Photo 16 – Tanks and Tank equipment moved for Clean-Up**

