


Inspection Photos
Location Name: Stroh 12-22
Location ID: 310848



Wellhead



Master valve leak