

Final Reclamation Inspection

December 21, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 329017

Inspection Document #: 697503590

Weld County, CO

SENE Section 36 T4N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017



Photo 1. Photo taken from the northwestern well location access road, facing South. Photo illustrates Operator has regraded the access road. There were no observed ruts.



Photo 2. Photo taken from the northwestern well location access road, facing North. See comments under Photo 1.

Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017



Photo 3. Photo taken from the northeastern well location access road, facing East. See comments under Photo 1.



Photo 4. Photo taken from the northeastern well location access road, facing South. See comments under Photo 1.

Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017



Photo 5. Photo taken from the well location, facing Southwest. Photo illustrates Operator has performed final reclamation activities to remove road base, import topsoil and contour. Staff did not inspect for decompaction.



Photo 6. Photo taken from the well location, facing Northwest. See comments under Photo 5.

Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017



Photo 7. Photo taken from the well location, facing West. See comments under Photo 5.

Inspection Photos
Location Name: HSR HANCOCK #8-36
Location ID: 329017



Photo 8. Photo taken from the tank battery, facing Southwest. Photo illustrates all unused equipment has been removed and weeds have been controlled.