

Inspection Photos  
Location Name: Huber-Lengal/Slaughter #2-10  
API: 05-067-08231



Huber-Lengal/Slaughter #2-10 location photo.



Concrete pad and gravel are wet and stained.

**Inspection Photos**  
**Location Name: Huber-Lengal/Slaughter #2-10**  
**API: 05-067-08231**



**Gravel is stained near exhaust piping.**



**Concrete beneath prime mover is wet and stained.**