

Inspection Photos
Location Name: Hunt 8-60-6A
Location ID: 454627



Photo 1 – Wellheads



Photo 2 – Sign at Entrance



Inspection Photos
Location Name: Hunt 8-60-6A
Location ID: 454627



Photo 3 – Tank Battery



Photo 4 – Separators



Inspection Photos
Location Name: Hunt 8-60-6A
Location ID: 454627



Photo 5 – Gas Lift Injection Meter House



Photo 6 – Compressor



Inspection Photos
Location Name: Hunt 8-60-6A
Location ID: 454627



Colorado Oil and Gas Conservation Commission
 40.69668, -104.13766, 4878.2ft, 158°
 12/30/2021 12:13:35

Photo 7 – Gas Sales Meter House



Colorado Oil and Gas Conservation Commission
 40.6967, -104.13766, 4875.7ft, 239°
 12/30/2021 12:14:40

Photo 8 – Gas Meter Calibration Card

Inspection Photos
Location Name: Hunt 8-60-6A
Location ID: 454627



Photo 11 – ECDs



Photo 12 – VRT and Tank Battery



Inspection Photos
Location Name: Hunt 8-60-6A
Location ID: 454627



Photo 13 – LACT