

**Inspection Photos**  
**Location Name: Hunt 8-60-6C**  
**Location ID: 454166**



**Photo 1 – Compressor**



**Photo 2 – Separators**



**Inspection Photos**  
**Location Name: Hunt 8-60-6C**  
**Location ID: 454166**



**Photo 3 – VRU and ECD**



**Photo 4 – LACT**





**Inspection Photos**  
**Location Name: Hunt 8-60-6C**  
**Location ID: 454166**




**Photo 5 – Tank Battery Sign**



**Photo 6 – Wellhead**



**Inspection Photos**  
**Location Name: Hunt 8-60-6C**  
**Location ID: 454166**



**Photo 7 – Wellhead**



**Photo 8 – Unmarked Riser at Separators**



**Inspection Photos**  
**Location Name: Hunt 8-60-6C**  
**Location ID: 454166**



**Photo 9 – Unmarked Risers between Separators and Compressor**



**Photo 10 – Compressor**



**Inspection Photos**  
**Location Name: Hunt 8-60-6C**  
**Location ID: 454166**



**Photo 11 – Gas Meters**