

Inspection Photos

Location Name: Johnston ET AL 20-1

Location ID: 322884

Jan 4, 2022 at 2:55:22 PM
40.033691,-104.682456
76 Frontage Rd
Hudson CO 80642
United States
COGCC



Pic 1 wellhead / pump jack

Jan 4, 2022 at 2:56:21 PM
40.033782,-104.682501
76 Frontage Rd
Hudson CO 80642
United States
COGCC



Pic 2 stained soil and trash by pumping unit motor



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Johnston ET AL 20-1

Location ID: 322884

Jan 4, 2022 at 2:56:59 PM
40.033719,-104.682604
76 Frontage Rd
Hudson CO 80642
United States
COGCC



Pic 3 ECD

Jan 4, 2022 at 2:57:09 PM
40.033630,-104.682651
76 Frontage Rd
Hudson CO 80642
United States
COGCC



Pic 4 gas meter run, vertical separator, horizontal separator



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Johnston ET AL 20-1
Location ID: 322884



Pic 5 stained soil and trash by motor



Pic 6 Stained soil and trash by motor



Inspection Photos
Location Name: Johnston ET AL 20-1
Location ID: 322884



Pic 7 unused equipment on side of motor house




Pic 8 tanks

Inspection Photos
Location Name: Johnston ET AL 20-1
Location ID: 322884

Jan 4, 2022 at 2:59:00 PM
40.033622,-104.682417
76 Frontage Rd
Hudson CO 80642
United States
COGCC



Pic 9 unused tank on location needs to be removed.



Pic 10 Annual calibration is not current for gas meter run