

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE

Location ID: 334996



Photo #5604 from entrance to location.

Photo #5605 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE

Location ID: 334996



Photo #5606 No battery sign located at the tank battery.



Photo #5607 Separator after fire.

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE-67S95W /20SESE

Location ID: 334996



Photo #5608 Separator after fire.



Photo #5609 Separator after fire.